




Givaudan Roure Corporation

**Remedial Action Report for
Sewer Decommissioning
*Clifton, New Jersey***

February 2000

22329.00.01

Environmental Resources Management
855 Springdale Drive
Exton, Pennsylvania 19341



ERM.

LIST OF PLATES

Plate 1	<i>Post-Excavation Sample Location Map</i>
Plate 2	<i>Supplemental Sewer Investigation Soil Boring Location Map</i>
Plate 3	<i>Sewer Sidewall Sample IGWSCC/RDCSCC Exceedances</i>
Plate 4	<i>Sewer Bottom Sample IGWSCC/RDCSCC Exceedances</i>
Plate 5	<i>Additional Excavation Findings IGWSCC/RDCSCC Exceedances</i>
Plate 6	<i>Supplemental Soil Investigation IGWSCC/RDCSCC Exceedances</i>

**Under the direction of Sarah Flanagan, ORC and
Robert Keating, Records Center Manager,
attachments were not scanned.**

Givaudan Fragrances Corp.

DIAMOND ALKALI SUPERFUND SITE

NJD980528996